



NTM 40/15 Wemyss Bay Ferry Terminal Linkspan Inspection

Categories : [Piers and harbours](#), [Uncategorized @gd](#)

Tagged as : [Ferry Terminal](#), [Linkspan](#), [Wemyss Bay](#)

Date : 28th July 2015

Mariners are advised that work to inspect the linkspan at Wemyss Bay Ferry Terminal is due to commence on Wednesday 29th July 2015, it is anticipated the inspection will be completed within one day.

CMAL's consulting engineers, CH2M Hill, will be operating from the pier deck and a workboat supplied by GSS Ltd. The inspection will be undertaken from a workboat which will operate around and under the structure.

The consultant's supervisor will liaise with the Port Manager and Masters of the CalMac Ferries to ensure there is no disruption to scheduled ferry services. VHF channel 16 will also be monitored.

All vessels navigating in the vicinity of Wemyss Bay Ferry Terminal must do so with caution and regulate their speed to minimise the effects of wash accordingly.

[Please click here to download a printable PDF of NTM 40/15](#) (442kb)

Further information can be obtained using the contact details

David McHardie
Harbour Master
Caledonian Maritime Assets Limited