



NTM 52/20 EAST LOCH TARBERT, ISLE of HARRIS AIDS TO NAVIGATION UPDATES

Categories : [Notice to Mariners](#)

Date : 16th September 2020

Mariners are advised that the following special mark buoy within inner East Loch Tarbert, Isle of Harris has been permanently withdrawn.

Location description	East Loch Tarbert. Tarbert. Moorings Special Mark Buoy
Latitude	57° 53.807' North (WGS-84 datum)
Longitude	006° 47.831' West (WGS-84 datum)
Character of light	Fl (4) Y 12s
Colour/Shape	Yellow conical buoy
Range	2 nautical miles

The fore and aft moorings this buoy marked have also been permanently removed.

To avoid restricting the area required for the ferry to manoeuvre mariners are requested not to anchor in the now vacated area that lies opposite the ferry terminal pier.

Mariners are further advised the Isle of Harris Marina pontoons are now returned to their original position and the following navigation light thereon has been re-established in position.

Location description	East Loch Tarbert. Tarbert. North Pontoon. A3994.09
Latitude	57° 53.815' North (WGS-84 datum)
Longitude	006° 48.018' West (WGS-84 datum)
Character of light	Fl (2) R 6s
Colour/Shape	Metal post
Range	2 nautical miles

Further details can be obtained using the contact details below.

David McHardie

Harbour Master

Caledonian Maritime Assets Limited

Municipal Buildings,

Fore St. Port Glasgow

PA1 4 5EQ

Tel: 01475 749 920

Issued on behalf of the Harbour Master

Caledonian Maritime Assets Limited