



# NTM 70/18 Gourock Ferry Terminal Firth of Clyde Linkspan Berth Fender Repair

Categories : [Uncategorized @gd](#)

Date : 13th August 2018

**Latitude** 55° 57.658? North (WGS-84 datum)  
**Longitude** 004° 48.887? West (WGS-84 datum)

Mariners are advised that works to repair an damaged fender located at the north end of the Linkspan Berth, Gourock Ferry Terminal, Firth of Clyde will commence this morning 13 August 2018.

Contractors will be operating from the shore and from a small workboat and works are scheduled to be completed within two days.

The works supervisor will liaise with the harbour manager and ferry Masters to avoid any disruption to scheduled services and will monitor VHF channels 12 and 16.

All vessels navigating in the vicinity of Gourock Ferry Terminal during this time are advised to proceed with caution and regulate their speed to minimise the effects of wash accordingly.

Further details can be obtained using the contact details below:

David McHardie  
**Harbour Master**

Caledonian Maritime Assets Limited  
Municipal Buildings, Fore St.,  
Port Glasgow  
PA1 4 5EQ  
Tel: 01475 749 920  
email: [info@cmassets.co.uk](mailto:info@cmassets.co.uk)