



NTM 24/19 Tiree Ferry Terminal Pierhead Fender Damaged

Categories : [Uncategorized @gd](#)

Date : 21st February 2019

Latitude **56° 30.612?** North (WGS-84 datum)
Longitude **006° 47.801?** West (WGS-84 datum)

Mariners are advised that a lower Trellex fender mounted on the northeast corner of Scarinish Pier roundhead, Tiree Ferry Terminal, Isle of Tiree has become detached.

To avoid further damage being caused to the fender support or to a vessel's hull it is requested Mariners take care when manoeuvring against the pier roundhead until further notice.

Further details can be obtained using the contact details below:

David McHardie
Harbour Master
Caledonian Maritime Assets Limited
Municipal Buildings,
Fore St. Port Glasgow
PA1 4 5EQ

Tel: 01475 749 920

Email: info@cmassets.co.uk