



NTM 105/18 Tobermory Ferry Terminal Isle of Mull Berthing Restrictions

Categories : [Uncategorized @gd](#)

Date : 11th December 2018

Latitude **56° 37.376?** North (WGS-84 datum)
Longitude **006° 3.824?** West (WGS-84 datum)

It has been reported to CMAL there are increasingly occasions when vessels berth at the Mishnish Pier, Tobermory Ferry Terminal, Isle of Mull, by rafting up on the outside of the ferry.

Due to the risk of contact damage between vessels and the possibility of exceeding the safe working capacities of the ferry or pier mooring equipment it is requested Mariners cease this activity with immediate effect.

Any vessels observed to continue this practice will be identified and further action may be taken.

David McHardie
Harbour Master

Caledonian Maritime Assets Limited
Municipal Buildings, Fore St.,
Port Glasgow
PA1 4 5EQ
Tel: 01475 749 920
email: info@cmassets.co.uk